

BELZONA IMPROVES WORKING CONDITIONS BY SEALING THE ROOF OF A CHOCOLATE FACTORY

CUSTOMER

MO, USA

APPLICATION DATE

March, 2008

APPLICATION SITUATION

Poorly insulated roof

PROBLEM

Minor leaks were causing unsanitary conditions in the kitchen and the HVAC system could not keep up with the major temperature and humidity fluctuations causing discoloration in the highly decorative chocolates.

PRODUCTS

Belzona 3111 (Flexible Membrane)

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Rubber

APPLICATION METHOD

The roof was pressure washed and the parapets were re-pointed with Belzona 4111. The roof was then completely sealed and protected with the Belzona 3111 system. The application was carried out in accordance with a modified version of Belzona System Leaflet RPA-10.

BELZONA FACTS

The owner remarked about the noticeable difference in temperature and humidity control after just the first coat of Belzona 3111 was applied.

PICTURES

1. Storefront image
2. The roof prepared and ready for application
3. Picture of the first 1/2 of sprayed Belzona 3111
4. Picture of finished installation of Belzona 3111, including repaired parapets



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA[®]
Repair • Protect • Improve