

## BELZONA WATERPROOFS FLASHINGS SAVING MILLIONS OF DOLLARS OF PRODUCT

### CUSTOMER

MO, USA

### APPLICATION DATE

August, 2004

### APPLICATION SITUATION

Roof flashings

### PROBLEM

The material used to seal the flashings on this firewall had become brittle and cracked, creating fissures for water to seep into the building. A solution was needed that was both flexible and UV stable to protect this pharmaceutical storage facility housing millions of dollars of product.

### PRODUCTS

Belzona 3111 (Flexible Membrane)  
Belzona 3921 (GSC Surface Conditioner)  
Belzona 9311 (Reinforcement Sheet)

### SUBSTRATE

Galvy/Metal

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-8 using the fully reinforced Belzona 3111 system.

### BELZONA FACTS

Due to past success with roof repairs for this pharmaceutical facility, Belzona was the confident choice. 850 linear feet of flashing was completely sealed and protected in two days. Inspected in 2012, the repair is still perfect.

### PICTURES

1. Picture of Warehouse/Storage Structure
2. Picture of the damaged flashing in need of repair
3. Close-up of Belzona application
4. Completed Belzona repair of 80 linear feet of flashing



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

