

## LEAKY ROOF REPAIRED WITH BELZONA DODGING A THUNDERSTORM

### CUSTOMER

Coal Mine, USA

### APPLICATION DATE

May 2006

### APPLICATION SITUATION

Roof leak

### PROBLEM

The warehouse roof leaked for over 20 years with 5 different contractors trying to fix it.

### PRODUCTS

Belzona 3111 (Flexible Membrane)

### SUBSTRATE

Steel

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-1.

### BELZONA FACTS

Belzona 3111 was used, dodging a thunderstorm in 3 weeks. It has not leaked a drop in 8 years now.

### PICTURES

1. Problem area
2. Application in progress
3. Complete application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve