

RUBBER LINER IN SLURRY PUMP REPAIRED WITH BELZONA

CUSTOMER

Quarry, Israel

APPLICATION DATE

February 2014

APPLICATION SITUATION

Rubber lined Warman 10/8M slurry pump.

PROBLEM

The rubber liner had suffered local damage resulting in an operational shut down.

PRODUCTS

Belzona 2311 (SR Elastomer)

SUBSTRATE

Rubber

APPLICATION METHOD

Application was carried out in accordance with Belzona Know How System Leaflet SHM-9.

BELZONA FACTS

The customer was able to run the pump the same day saving shut down costs of 7 days whilst waiting for new replacement liner.

PICTURES

1. Damaged rubber liner
2. The Warman 10/8M pump
3. Damaged area Conditioned with Belzona 2911 (Elastomer QD Conditioner)
4. Rubber liner after application of Belzona 2311



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve