

## BELZONA REFURBISHMENT OF FLAT ROOF

### CUSTOMER

School, Grantham, UK

### APPLICATION DATE

2013

### APPLICATION SITUATION

Large areas of flat roof over the sports and dining areas.

### PROBLEM

The felt roof had deteriorated allowing numerous leaks into the areas below.

### PRODUCTS

Belzona 3111 (Flexible Membrane)

### SUBSTRATE

Felt

### APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflets RPA-1, RPA-6 and RPA-8. After cleaning the roof and carrying out some localised repairs, a fully reinforced Belzona 3111 system was applied to the entire roof areas.

### BELZONA FACTS

Client had already used Belzona on various roofing projects in the past and was happy with the system. The use of Belzona allows the roofs to be upgraded with minimal disruption.

### PICTURES

1. Section of roof before work started
2. Completed application
3. Upper section of roof before coating
4. Completed application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve