

## BELZONA REBUILDS DAMAGED STONework

### CUSTOMER

School, West Yorkshire, UK

### APPLICATION DATE

Summer 2013

### APPLICATION SITUATION

Weathered stonework on school building.

### PROBLEM

Weathered stonework needed rebuilding to improve appearance and remove risk of falling debris.

### PRODUCTS

Belzona 4141 (Magma-Build)

### SUBSTRATE

Stone

### APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet WPA-4. The substrate was hand prepared to remove any loose material. This was followed by application of Belzona 4911 (TX Conditioner) before Belzona 4141 was applied. This material was shaped by hand to match in with the existing stonework.

### BELZONA FACTS

Due to the health and safety implications of the situation, the client required a solution to be carried out as soon as possible in order to eliminate any potential accidents. Belzona were able to facilitate this, carrying out a site survey and conducting the application over a course of just two weeks.

### PICTURES

1. Before application
2. Local repair to corbel with shape detail
3. Completed application to corbel
4. Completed application to window sill



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

