

GARBAGE ROOM FLOOR REPAIR AND COATING AT A MALL

CUSTOMER

Burlington, Ontario, Canada

APPLICATION DATE

August 2012

APPLICATION SITUATION

Garbage room floors.

PROBLEM

A combination of waste causing chemical attack and physical damage caused by large roll on, roll off containers.

PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. The surface was prepared by removing any existing coating and loose material or contamination and abraded to expose the aggregate. Belzona 4131 was applied to rebuild and repair the damaged concrete. Belzona 5231 was applied to the garbage room floor with a roller in accordance with Belzona Instructions For Use.

BELZONA FACTS

The repairs and coating provide resistance to the daily activities, wear and attack. Eighteen months after application (March 2014) the system is performing excellent.

PICTURES

1. Flooring prior to application
2. Application in progress
3. Complete application
4. Eighteen months after application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve