

BELZONA REPAIRS DAMAGED CONCRETE FLOOR

CUSTOMER

Textile manufacturer, Rochdale, UK

APPLICATION DATE

February 2014

APPLICATION SITUATION

About 28m² of concrete floor in textile plant exposed to regular forklift truck traffic.

PROBLEM

The floor was suffering from heavy wear in localised areas due to the heavy forklift truck traffic present on the site. This had caused damage to numerous areas of the concrete with a loss of depth in some areas of up to 10mm.

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. A mechanical plane and cutter were used to remove the concrete substrate in the designated areas down to a minimum depth of 6mm before it was conditioned with Belzona 4911. The surface was then rebuilt with Belzona 4111 finishing flush with the surrounding areas.

BELZONA FACTS

Belzona was able to carry out the application over the course of a weekend, allowing the facility to be back in service for 6:30am Monday morning. The repair procedure ensured a smooth transition between original floor areas and the repair.

PICTURES

1. Damaged concrete floor
2. Application of Belzona 4111
3. & 4. Completed repair



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com

The Belzona logo, consisting of a stylized molecular structure above the word 'BELZONA' in bold, capital letters.
BELZONA
Repair • Protect • Improve