

SPALLED STEPS NO LONGER A SAFETY HAZARD WITH BELZONA REPAIR

CUSTOMER

Waterloo, ON, Canada

APPLICATION DATE

September 2014

APPLICATION SITUATION

Stairs to a memorial recreation center.

PROBLEM

The stairs had spalled due to environmental freeze and thaw effect.

PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-10 for fixing or securing anchor bolts or hand rails. The surface was prepared using a grinder and the surface was brushed to remove any loose concrete. Belzona 4911 was applied to the area using a stiff bristle brush. Belzona 4131 was applied directly onto the conditioned surface in accordance with Belzona Instructions For Use.

BELZONA FACTS


Belzona 4131 has outstanding environmental protection, is impermeable to water and provides long term protection. Belzona 4131 is easily applied using a trowel, thus, no specialist tools are required.

PICTURES

1. Prior to application
2. Completed application
3. Completed application



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve