

BELZONA SMOOTHS AIRPORT RUNWAY

CUSTOMER

Airport, Northern Texas, USA

APPLICATION DATE

2014

APPLICATION SITUATION

Airport runway

PROBLEM

Prior patching material failed. A steel plate was used to cover the hole.

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA. Old and loose material was removed. Then, a mixture of gravel and Belzona 4111 was used to bulk up the patch. A batch of pure Belzona 4111 was used to finish the job.

BELZONA FACTS

The material was applied at 11:00 PM and the runway was open by 8:00 AM.

PICTURES

1. Old patch failed and removed
2. Hole prepared for application
3. Bulk material to fill the hole
4. Finished with pure Belzona 4111



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve