

CONCRETE STEP REPAIR WITH BELZONA

CUSTOMER

Building & Structures, North Carolina, USA

APPLICATION DATE

August 2015

APPLICATION SITUATION

Concrete steps leading up to the entrance of building.

PROBLEM

Concrete steps were broken and deteriorating.

PRODUCTS

Belzona 4411 (Granogrip)

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

APPLICATION METHOD

The old concrete was removed so that Belzona 4111 could fill in the spots. After the steps were smoothed over, Belzona 4411 was added with some aggregate.

BELZONA FACTS

This entranceway was an eyesore and a trip hazard. The use of Belzona products provided a solution to both issues in a cost effective manner. This area is used frequently for special events, such as private catering and weddings.

PICTURES

1. Prior to application
2. Preparing the surface by removing busted concrete
3. Application of Belzona 4411 with some aggregate
4. Completed application




1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com

