

LIVE WATER LEAK CLAMPED WITH BELZONA

CUSTOMER

Hospital, Northern Texas, USA

APPLICATION DATE

2011

APPLICATION SITUATION

Hot water line at a hospital

PROBLEM

The hot water line was leaking from an expansion tank to the 2" line. The supply of hot water could not be shut off since it fed water to the emergency room.

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel Pipe

APPLICATION METHOD

A clamp was fabricated at a machine shop. The clamp had a threaded drain and matched threaded fittings. Belzona 1111 was applied to secure clamp to the hot water line.

BELZONA FACTS

This saved a major disruption to the hospital's emergency room. There was no alternative solution except replacement.

PICTURES

1. Leaking pipe cleaned
2. Clamp ready to go
3. Application of Belzona 1111
4. Clamp installed



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve