Know-How*in Action*

Vol.XXX No.68

BELZONA TANK BASE SEALING SYSTEM OFFERS COST-EFFECTIVE SOLUTION

CUSTOMER
International Petroleum Company, China

APPLICATION DATE
October 2014

APPLICATION SITUATION
Storage tank at tank farm.

PROBLEM
The original tank base seal cracked allowing moisture penetration to tank base. This led to corrosion under the tank base.

PRODUCTS
Belzona 3211 (Lagseal)

SUBSTRATE
Carbon steel and concrete

APPLICATION METHOD
The application was carried out in accordance with Belzona Know-How System Leaflet GSS-3.

BELZONA FACTS
The Belzona system met the clients' urgent requirement for a system to resist water, weather and fire. The cost effective Belzona system has been specified into the client's global standard and all the 40 tanks at the farm are to be protected in 2 years.

PICTURES
1. Overview of the tank farm
2. Damaged tank base
3. Applying Belzona 3211
4. Completed application

1.

2.

3.

4.

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2015