

## BELZONA REPAIRS FLOOR CRACKS CAUSED BY A ZAMBONI

### CUSTOMER

Kitchener, ON, Canada

### APPLICATION DATE

August 2013

### APPLICATION SITUATION

Floor leading to rink access used by a Zamboni.

### PROBLEM

Cracks and pitting caused by studded tyres of a Zamboni.

### PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 4911 (Magma TX Conditioner)

### SUBSTRATE

Concrete

### APPLICATION METHOD


The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1 for rebuilding worn and damaged floor surfaces. The surface was prepared by removing all loose concrete and a high pressure washer was used to remove any contamination. After preparation of the surface, Belzona 4911 was applied to achieve maximum adhesion. Then, Belzona 4131 was applied using a trowel in accordance with the Belzona Instructions For Use.

### BELZONA FACTS

Belzona 4131 is a high performance non-porous resurfacing material that provides excellent protection against the effects of abrasion, impact, vibration and chemical attack. This system is easy to use as no specialist tools are required. The customer was very satisfied with the application.

### PICTURES

1. Prior to application
2. Surface preparation in progress
3. Application in progress
4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve