

## BELZONA REPAIRS HOLE ON SCUM TANK

### CUSTOMER

Toronto, ON, Canada

### APPLICATION DATE

November 2014

### APPLICATION SITUATION

Scum tank at a water pollution control plant.

### PROBLEM

Hole caused by corrosion.

### PRODUCTS

Belzona 1161 (Super UW-Metal)

Belzona 9111 (Cleaner Degreaser)

### SUBSTRATE

Steel

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet HEX-9 for repairing leaking pipework. The surface was prepared using a grinder to roughen the surface and Belzona 9111 was used to clean the area. Belzona 1161 was applied around the hole and then a piece of metal was placed over the product. Once the piece of metal is in place, Belzona 1161 was applied around the pipe in accordance with Belzona Instructions For Use.

### BELZONA FACTS

Belzona 1161 bonds firmly to oily, wet and not fully prepared substrates. This system is simple to use and does not require specialist tools. By using Belzona 1161, the customer eliminated expensive replacement costs and minimized downtime.

### PICTURES

1. Prior to application
2. Preparation in progress
3. Application in progress
4. Completed application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve