

## BELZONA SEALS NEW PIPES IN HOTEL WATER RESERVOIR

### CUSTOMER

Hotel, Israel

### APPLICATION DATE

2013

### APPLICATION SITUATION

New piping of a hotel water reservoir

### PROBLEM

New pipes drilled into the water reservoir needed to be anchored and sealed to the tank wall.

### PRODUCTS

Belzona 4111 (Magma Quartz)

### SUBSTRATE

Carbon Steel , Concrete

### APPLICATION METHOD

Application carried out in accordance with Belzona Know How System Leaflets FPA-5

### BELZONA FACTS

The costumer was looking for a reliable solution since all the previous repairs resulted in leaks around the pipes. Belzona 4111 provides high bond strength without shrinking enabling a secure leak free installation.

### PICTURES

1. & 2. Internal application to secure new pipes
2. & 4 External fixing of pipes



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve