

## BELZONA ELIMINATES TRIP HAZARD FROM DRAIN COVERS

### CUSTOMER

Shopping centre, Bankstown, Australia

### APPLICATION DATE

May 2004

### APPLICATION SITUATION

Drain covers in various areas of shopping centre.

### PROBLEM

Existing drain covers were proud of surface creating a potential trip hazard.

### PRODUCTS

Belzona 4111 (Magma Quartz)

Belzona 4411 (Granogrip)

### SUBSTRATE

Concrete

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know- How System leaflets FPA-1 & FPA-8. Concrete was ground away and Belzona 4111 used to re-install plates at ground level. Plates were then coated with Belzona 4411 Granogrip to provide slip resistance.

### BELZONA FACTS

The finished outcome eliminated the trip hazard and installation did not impact on normal operations around the shopping centre.

### PICTURES

1. The raised drain plate
2. Belzona 4111 to rebuild drain
3. The plate fixed in place
4. Coated with Belzona 4411



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve