

## BELZONA REPAIRS CONCRETE AFTER BOLLARD REMOVAL

### CUSTOMER

Shopping Centre, Bankstown, Australia

### APPLICATION DATE

September 2004

### APPLICATION SITUATION

Damaged concrete in 48 areas where bollards were removed

### PROBLEM

Removal of bollards left rough concrete substrate that was a trip hazard.

### PRODUCTS

Belzona 4111 (Magma Quartz)

### SUBSTRATE

Concrete

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know How System Leaflet FPA-1.

### BELZONA FACTS

Ability to feather edge the Belzona 4111 enabled damaged areas to be quickly and simply levelled to eliminate trip hazard.

### PICTURES

1. Damaged concrete
2. Conditioner applied
3. Mixing Belzona 4111
4. Applying Belzona 4111



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve