

BELZONA SAFETY FLOORING AROUND MIXER

CUSTOMER

Ceramics producer, Gliwice, Poland

APPLICATION DATE

May 2011

APPLICATION SITUATION

The floor lined with rubber lining around a mixer handling Glycol and other additives.

PROBLEM

The floor was covered with a rubber lining which was very slippery when Glycol was spilt on it. One worker had broken a foot after slipping on the floor.

PRODUCTS

Belzona 4111 (Magma Quartz)

Belzona 4411 (Granogrip)

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet FPA-8. After removing rubber sheets and cleaning the concrete, Belzona 4111 was used to level the concrete before applying the Belzona 4411 non-slip system.

BELZONA FACTS

After application of Belzona 4411 floor is safe and there have been no more slips. Belzona 4411 provides a chemical resistant surface that makes clean-up of spills easy whilst providing a positive grip surface to prevent slips.

PICTURES

1. Grinding concrete floor
2. Repair of damage and filling cavities with Belzona 4111
3. Application of Belzona 4411
4. General view of the floor after application of Belzona 4411 system



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve