

## BELZONA CURES DRUG FACTORY FLOOR

### CUSTOMER

Pharmaceutical company, Warsaw, Poland

### APPLICATION DATE

June 2013

### APPLICATION SITUATION

Very damaged and cracked concrete floor in the medicines factory.

### PROBLEM

The cracks collect a lot of bacteria and contaminants creating a serious hygiene issue.

### PRODUCTS

Belzona 4111 (Magma Quartz)

Belzona 5811 (immersion Grade)

### SUBSTRATE

Concrete

### APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflets FPA-1 and FPA-3.

### BELZONA FACTS

Belzona system enabled floor repairs to be carried out with minimal disruption to production in adjoining areas. Belzona repair provided a smooth, easy-to-clean, hygienic surface suitable for pharmaceutical production.

### PICTURES

1. View of damaged warehouse floor
2. Close up of the cracked concrete
3. & 4. The floor after application of Belzona 5811



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve