

BELZONA 1111 REBUILDS TOWBOAT DRIVE

CUSTOMER

WA, USA

APPLICATION DATE

July, 2017

APPLICATION SITUATION

Erosion damage to the cast steel housing of this Schottel drive on a towboat.

PROBLEM

After 64,000 hours of operation, a fair amount of erosion had occurred starting to compromise the mating face of this drive unit. Up to 1.5 inches of missing steel in the worst places.

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Cast steel

APPLICATION METHOD

The area of application was grit blasted with alumina oxide for a rough clean finish. MEK was used to wash the area. The first layer of Belzona 1111 was applied with a short bristle brush to work it into the rough open pores for optimal adhesion. Slowly, mixing smaller batches at a time, the areas were rebuilt. This allowed for the deeper areas to be filled in a risk of slump as the prior layers were setting up while the next layer was applied. After the application was complete, the team waited till the next day to hand finish the application with sandpaper, emery cloth, and flat boards.

BELZONA FACTS

It takes 2 years and several tens of thousands dollars to get a set of these drive units made and delivered. This application took a mere 2 hours to complete, with no more than another 2 hours to finish off. The entire unit will be over-coated with Belzona 1331 after it is assembled.

PICTURES

1. Original condition showing erosion.
2. Blasted and ready for the application.
3. Partially completed.
4. Application complete.



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

