

ROOF OF AN ART DECO BUILDING SAVED WITH BELZONA

CUSTOMER

Lancashire, England, UK

APPLICATION DATE

2016

APPLICATION SITUATION

Large bitumen felted flat roof on a beautiful Art Deco Public Building.

PROBLEM

The roof is a large expanse with several separate roof areas on different levels. There were numerous leak areas through the existing roofing felt that required repair to prevent permanent damage to the wonderful interior which is still used for numerous events on a regular basis including ball room dancing.

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Bitumen felt

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, 6, 8 & 10

BELZONA FACTS


This was a very large area with lots of upstands and gutter detail situated in a very aggressive environment right next to the coast with strong winds, sea, salt and sand constantly attacking the building. The Customer required a product that was capable of handling all the complex roof details and all the elements could throw at it whilst at the same time proving them with long term value for money. Belzona could tick all these boxes.

PICTURES


1. Overview of the building.
2. One small section of the roof before.
3. The same small section after application of Belzona 3111.
4. Belzona 3111 coated section close to the dome area.



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve