

BELZONA SEALS PARAPET WALL

CUSTOMER

Shopping Centre, NSW, Australia

APPLICATION DATE

July 2004

APPLICATION SITUATION

Parapet wall on the roof of a Shopping Centre

PROBLEM

Ingress of water into the building below caused by failed sealant on the parapet wall joints.

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Concrete & Asphalt

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet RPA-8. A fully reinforced Belzona 3111 system was applied to bridge between roof deck and wall.

BELZONA FACTS

Belzona 3111 was used for its easy application and ability to seal multiple substrates whilst coping with the differential movement present at the flashing.

PICTURES

1. Preparation in progress
2. Surface Conditioner applied
3. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA®
Repair • Protect • Improve