

BELZONA PROTECTS SETTLEMENT TANK

CUSTOMER

Pharmaceutical Company, Slovakia

APPLICATION DATE

2010

APPLICATION SITUATION

Damage to the tank and mixing equipment

PROBLEM

Erosion/corrosion damage was affecting the normal operation of the equipment

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Steel

APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflet TCC 3.

BELZONA FACTS

The Customer required a fast, high quality solution to repair the basin. Belzona provided an effective solution to not only repair the basin and mixing apparatus, but also protect it in the long term, extending the lifetime. Spraying enabled the application to be completed within the available window.

PICTURES

1. Mixing Basin
2. Extent of damage to the basin
3. Blasting of the basin
4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve