

BELZONA SUPERWRAP ALLOWS DRILLING TO CONTINUE

CUSTOMER

Azerbaijan

APPLICATION DATE

November 2017

APPLICATION SITUATION

A platform off the coast of Baku had to stop drilling due to wall loss on the HP mud lines. The problem areas were on 3 bend sections.

PROBLEM

Due to long lead time fabricating new sections of pipe, Belzona SuperWrap was used to reinstate the required strength to keep the high pressure lines in operation for at least 1 year.

PRODUCTS

Belzona SuperWrap II

SUBSTRATE

ASTM A 519 Gr 4130

APPLICATION METHOD

As per Belzona SuperWrap training

BELZONA FACTS

Drilling needed to commence immediately and due to long lead time to replace the pipe sections, Belzona SuperWrap was able to give the required up time.

PICTURES

1. View of Pipe before 21 wraps.
2. View of Pipe before 12 wraps.
3. View of SuperWrap repair: 21 wraps.
4. View of SuperWrap repair: 12 wraps.



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve