

BRISBANE CITY CENTER STEPS MADE SAFE BY BELZONA

CUSTOMER

Brisbane City Centre, Australia

APPLICATION DATE

2017

APPLICATION SITUATION

An overhanging step in the centre of Brisbane had become worn and caused broken and loose concrete to cause a trip hazard.

PROBLEM

This damaged step was proving rather dangerous as there was a large volume of pedestrian traffic in the area.

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet FPA-5. Initially, the broken step was demolished, before rebar was drilled and inserted to provide additional strength. The area was correctly prepared and Belzona 4111 was applied into the specially-constructed form-work.

BELZONA FACTS

The client was familiar with Belzona from other similar repairs and understood the benefits of the concrete repair materials over their traditional counterparts. In fact, the repair only took one day to complete, with the former removed the following day, allowing the step to be available to pedestrians very quickly.

PICTURES

1. Broken step.
2. Loose concrete removed.
3. Former installed.
4. Completed repair back in service.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA[®]
Repair • Protect • Improve