

BELZONA WEATHERPROOFS AIRPORT FIRE STATION ROOF

CUSTOMER

Airport, UK

APPLICATION DATE

May 2003

APPLICATION SITUATION

Airport fire station roof

PROBLEM

This fire station roof was leaking and the local airport authority wanted to repair it and extend its life, rather than a full replacement.

PRODUCTS

Belzona® 3131 (WG Membrane)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona® System Leaflet RPA-1

BELZONA FACTS


The unusual construction of this roof posed a problem for other roofing systems. Belzona was chosen as the solution, as the alternative was to completely replace the roof. 2 years on and the application is still in perfect condition.

PICTURES

1. Roof to be coated
2. The roof after cleaning and surface preparation
3. Coated roof
4. Completed application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA®
Repair • Protect • Improve