

BELZONA CURES DAMP WALLS

CUSTOMER

Private Residence, North Yorkshire, UK

APPLICATION DATE

2016

APPLICATION SITUATION

Private residence

PROBLEM

Recurring damp was causing damage to the interior and subsequent remedial works. Several solutions had been tried in the past but they had failed to solve the problem. The cause of the damp was not obvious and after seeking professional advice from several sources, the customer was advised that driving rain was the most likely cause.

PRODUCTS

Belzona® 5151 (Hi-Build Cladding)

SUBSTRATE

Brick

APPLICATION METHOD

Application carried out in accordance with Belzona system leaflet WPA-1

BELZONA FACTS

It was found that the previous coating had numerous defects that allowed water to become trapped, causing the damp. The flexibility and microporous properties of Belzona 5151 allow moisture to escape while preventing further ingress. Since applying the Belzona 5151 the client has not had any problems.

PICTURES

1. House before application
2. Damage to interior
3. Ineffective existing coating
4. Completed application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve