

BELZONA IMPROVES SAFETY WITH GRIP SYSTEM

CUSTOMER

Factory, Kirkop, Malta.

APPLICATION DATE

May 2013

APPLICATION SITUATION

Factory main entrance steps.

PROBLEM

Marble stairs were very slippery, especially in wet conditions.

PRODUCTS

Belzona 4411 (Granogrip)

Belzona 9221 (Surefoot Aggregate White)

SUBSTRATE

Marble

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. The steps were marked and the nosing ground with carbide discs. After masking off all the steps, Belzona 4411 was brushed on and sprinkled with Belzona 9221.

BELZONA FACTS

The previous solutions of abrading the nose or stick on strips had proved to be ineffective. Belzona 4411 reduced the potential for accidents as well as creating an aesthetically pleasing finish.

PICTURES


1. Abraded nosing resulted in a non-effective solution
2. Nosing ground by carbide discs
3. Area masked off
4. Completed application




1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve