

PARKS AND RECREATION RESTROOM FLOOR COATED WITH BELZONA

CUSTOMER

Montana, USA

APPLICATION DATE

May 2017

APPLICATION SITUATION

Rest area needed to be sealed to allow cleaning and disinfecting of public access area. Porous concrete can harbor biological growth.

PROBLEM

Customer has numerous restrooms in public areas that are porous and cannot be disinfected efficiently.

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

APPLICATION METHOD


The application was carried out in accordance with a modified version of Belzona System Leaflet FPA-3. The floor was ground with diamond grinders. Within the overcoat windows two full coats of Belzona 5811 were applied.

BELZONA FACTS

The hard sealed surface allows cleaning crews to clean the restroom much easier, saving man hours and chemical use. Applying the Belzona coating has made the public access safer, cleaner and more pleasant.

PICTURES

1. Performing floor grinding preparation.
2. Surface edge and floor grinding complete.
3. Belzona 5811 application complete.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA®
Repair • Protect • Improve