# BELZONA PROVIDES INTERNAL LINING TO NEW SLURRY THICKENER

# **CUSTOMER**

Chemical Plant, Italy

## **APPLICATION DATE**

September 2017

## **APPLICATION SITUATION**

New construction slurry thickener 5 meters in diameter to be used to improve/renew part of production in a chemical plant.

#### **PROBLEM**

Request for internal protective coating, resistant to high temperature chemical attack.

#### **PRODUCTS**

Belzona 1593

## **SUBSTRATE**

Carbon Steel

## **APPLICATION METHOD**

Application carried out in accordance with Belzona System Leaflet SHM-13.

## **BELZONA FACTS**

Belzona 1593 proved to be the only product able to withstand the required service, allowing the customer to avoid high production costs in fine alloys, simplifying and decreasing production times of the equipment

# **PICTURES**

- 1. Internal view
- 2. DFT Inspection
- 3. Spark test
- 4. Completed application









For more examples of Belzona Know-How In Action, please visit http://khia.belzona.com



UK • USA • Canada • Thailand
www.belzona.com

BELY

Repair • Protect