

BELZONA REBUILDS AND PROTECTS PUMP CASING AND IMPELLER

CUSTOMER

Port Said, Egypt

APPLICATION DATE

March 2007

APPLICATION SITUATION

Pump casing and impeller

PROBLEM

Pump casing and impeller had become damaged due to erosion-corrosion

PRODUCTS

Belzona 1311 (Ceramic R Metal)

Belzona 1321 (Ceramic S Metal)

SUBSTRATE

Carbon Steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets CEP-1 and CEP-3.

BELZONA FACTS

Belzona 1321 provides excellent abrasion resistance and will completely eradicate the threat of corrosion.

PICTURES

1. Original Damage
2. Belzona 1311 completed application
3. Belzona 1321 application
4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve