

## CORROSION PROTECTION OF TWO INDUSTRIAL STORAGE TANKS WITH BELZONA 5811

### CUSTOMER

Poland

### APPLICATION DATE

2019

### APPLICATION SITUATION

Corrosion protection for 2 DEMI water tanks (Total area - 1520 m<sup>2</sup>, 2000 m<sup>3</sup>)

### PROBLEM

Corrosion on the internal linings of two large storage tanks at a large industrial plant in Poland.

### PRODUCTS

Belzona 5811 (Imersion Grade)

### SUBSTRATE

Steel

### APPLICATION METHOD

The application of Belzona 5811 was completed in accordance with Belzona Know-How System Leaflet TCC-5.

### BELZONA FACTS

Long-term protection against corrosion on the tanks.

### PICTURES

1. One of the storage tanks to be coated
2. Belzona 5811 applied internally
3. Testing coverage
4. Application complete on the internal lining



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

Copyright © Belzona International Limited 2019

  
**BELZONA**  
Repair • Protect • Improve