# BELZONA REFURBISHES SCHOOL ROOF

### **CUSTOMER**

Warwickshire, UK

## **APPLICATION DATE**

September 2011

#### **APPLICATION SITUATION**

Hall/Classroom roof at a School

#### **PROBLEM**

Due to age and cracks in both the parapet walls and in the ashfelt the roof was leaking into the classrooms below.

#### **PRODUCTS**

Belzona 3131 (WG Membrane) Belzona 9361 (Reinforcing Sheet)

### **SUBSTRATE**

Ashfelt

#### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-6 and RPA-10  $\,$ 

### **BELZONA FACTS**

School were so happy with the Belzona repair that they have now had another flat roof coated and some steps repaired with Belzona.

### **PICTURES**

- 1. Before repair
- 2. Before application
- 3. Completed application
- 4. Completed application









For more examples of Belzona Know-How In Action, please visit http://khia.belzona.com



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

