

BELZONA REFURBISHES OLD WEATHERED INDUSTRIAL ROOF

CUSTOMER

Miami, Florida. USA

APPLICATION DATE

April 2020

APPLICATION SITUATION

The raining season was about to begin and this roof had several leaks and deteriorated areas that were potentially going to become problematic

PROBLEM

Numerous water leaks and deteriorated roof

PRODUCTS

Belzona 3911
Belzona 3921
Belzona 3111
Belzona 9311

SUBSTRATE

Roofing Asphalt

APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflets RPA-1 and RPA-8. Surface was cleaned via pressure washing. Belzona 3911 was applied with a brush as a primer over the entire roof and belzona 3921 was applied over any metallic substrate. Belzona 3111 was spray applied over the horizontal surfaces and brush applied over seams and difficult geometries. Belzona 9311 sheet was additionally applied to problem areas such as joints, seams and glazing bars as additional reinforcement.

BELZONA FACTS

Belzona 3111 was chosen over other alternatives solutions because of their compliance with stringent standard ASTM D6083. The owner was very pleased with the final outcome and is thinking of progressively coating all of their roofing areas.

PICTURES

1. Roof before product application
2. Surface preparation via pressure cleaning
3. Mesh being applied over joint
4. The finished area



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2020


BELZONA[®]
Repair • Protect • Improve