

INDUSTRIAL FLOOR COATED WITH BELZONA

CUSTOMER

Poland

APPLICATION DATE

Aug-21

APPLICATION SITUATION

Maintaining the required hygiene and cleanliness of the production hall. Unevenness of the floor surface and damage to the pedestals arose as a result of intensive vehicular traffic of internal transport.

PROBLEM

Degradation of the floor surface could lead to the occurrence of potentially dangerous events, i.e. overturning the trolley, tripping within the production hall.

PRODUCTS

Belzona 4111 (Magma-Quartz)

Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

APPLICATION METHOD

Replenishment of cavities, repair of the floor surface, making a new smooth washable surface. Low-cost technology compared to traditional methods, applied in accordance with Belzona system leaflet FPA-3.

BELZONA FACTS

The client can be assured that when washing with chemicals they will not have to worry about the degradation of the coating or concrete.

PICTURES

1. Damaged floor to be repaired with Belzona 4111
2. Vacuuming up any loose debris and dust.
3. Roller Brush Application of Belzona 5231
4. Completed Application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2021


BELZONA
Repair • Protect • Improve