

## BELZONA PROTECTS PUMPS FOR WATER TREATMENT PLANT

**CUSTOMER**  
US

**APPLICATION DATE**  
2021

**APPLICATION SITUATION**  
Water treatment pumps required protection

**PROBLEM**  
Pump linings suffer from erosion and corrosion over time due to exposure to the process stream. A lining resistant to erosion was required

**PRODUCTS**  
Belzona 1331

**SUBSTRATE**  
Steel

**APPLICATION METHOD**  
Belzona 1331 was applied to the grit-blasted internals of the pumps

**BELZONA FACTS**  
This was the second set of pumps to be protected by Belzona as they had no problems with their first set upon inspection, a few years after the initial installation.

**PICTURES**  
1. -3. Completed application

1.



2.



3.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © Belzona International Limited 2021

  
**BELZONA®**  
Repair • Protect • Improve