

BELZONA COMPOSITE FERRY WRAP

CUSTOMER

France

APPLICATION DATE

Nov-17

APPLICATION SITUATION

Ferry Pipe

PROBLEM

Suffering from external corrosion

PRODUCTS

Belzona 1121 (Super XL-Metal)

Belzona 5821

SUBSTRATE

Mild Steel

APPLICATION METHOD


The application was carried out in accordance with Belzona system leaflet VPF-11. This was followed by over-coating with Belzona 5821.

BELZONA FACTS

The customer required a solution that was quick in order to get back into service.

PICTURES

1. Damaged pipe
2. Belzona 1121 wrap in progress
3. Composite Wrap complete
4. Completed application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2021


BELZONA[®]
Repair • Protect • Improve