

CYCLONE COATING PROTECTION WITH BELZONA

CUSTOMER

Slovakia, starch factory

APPLICATION DATE

2011

APPLICATION SITUATION

Milled corn material suffers and also adheres on the cyclone surface.

PROBLEM

Damaged cyclone

PRODUCTS

Belzona 1812 (Ceramic Carbide FP)

SUBSTRATE

Steel

APPLICATION METHOD

Application was carried out in accordance with modified Belzona System Leaflet SHM- 13

BELZONA FACTS

Conventional welding to be out of service too long and also it is not long lasting solution.

PICTURES

1. Ready for repair
2. Belzona 1812 application
3. Belzona 1812 application detail

1.



2.



3.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2021


BELZONA[®]
Repair • Protect • Improve