

BELZONA PUMP SEATING REPAIR

CUSTOMER

Slovakia, metallurgic plant

APPLICATION DATE

2014

APPLICATION SITUATION

After long time operation the pump has worn down seating. Result is a big clearance of the bearing.

PROBLEM

Corrosion, mechanical damage

PRODUCTS

Belzona 1111

SUBSTRATE

Iron casting

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet CEP - 2

BELZONA FACTS

Welding of the seating is very difficult, takes a long time. Belzona solution means very good repair and result is that customer uses this Belzona repair also for another pumps.

PICTURES

1. Damaged pump seating
2. Machining of the Belzona 1111
3. Ready for customer



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2021


BELZONA[®]
Repair • Protect • Improve