

BELZONA REPAIRS SUBWAY HANDRAIL

CUSTOMER

Subway Station in Quebec, Canada

APPLICATION DATE

March 1993

APPLICATION SITUATION

Handrail of escalator at a subway station

PROBLEM

Due to vandalism, a chunk of rubber was missing from the handrail.

PRODUCTS

Belzona® 2311 (SR-Elastomer)

SUBSTRATE

Rubber and nylon fabric

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet SHM-1.

BELZONA FACTS

The repair was completed with \$50.00 of Belzona product. The alternative was hot vulcanizing which would have shut the escalator down for one day and cost approximately \$2,000. The repair took only two hours to perform, and after three years, is still in operation today.

PICTURES

1. The damage due to the vandalism
2. Application of Belzona® 2311 in progress
3. The finished repair ready for operation



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

