

BELZONA PROTECTS LIKE NO OTHER

CUSTOMER

Chemical manufacturing company, Florida - USA

APPLICATION DATE

April 2005

APPLICATION SITUATION

Protect new containment for concentrated acid storage tanks

PROBLEM

Old containment's rubber liner had failed from use and UV damage. Protection of new containment was required for continued use of acid mix down plant.

PRODUCTS

Belzona® 4141 (Magma-Build)

Belzona® 4911 (Magma TX Conditioner)

Belzona® 4311 (Magma CR1)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-3 and TCC-15.

BELZONA FACTS

Storage of 98% sulfuric Acid and concentrated hydrochloric acid and mix down tanks for bottling of Muratic pool acid requires capacity for full containment of these acids as required by governmental mandates in many parts of the world.

PICTURES

1. General view of the area
2. Belzona® 4911 and Belzona® 4141 applied
3. Belzona® 4311 coat interrupted
4. Belzona® 4311 applied over night, completing the application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

