

BELZONA PROTECTS CONDENSER TUBE SHEET

CUSTOMER

Power plant, Egypt

APPLICATION DATE

January 2004

APPLICATION SITUATION

Steam unit condensers at a large power station.

PROBLEM

Corrosion of the tube sheets of two condensers.

PRODUCTS

Belzona® 1321 (Ceramic S-Metal)

SUBSTRATE

Steel

APPLICATION METHOD

Application was carried out in accordance with Belzona know-How system leaflet HEX-3.

BELZONA FACTS

Belzona provided long term protection, increasing the life of the tube sheet, decreasing other repairing and maintenance costs.

PICTURES

1. General view of the Condenser
2. The corroded tube sheet
3. Applying Belzona® 1321 to the tube sheet
4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

