

MAKE HAY WHILE THE SUN SHINES

CUSTOMER

Farmer - Kansas U.S.A.

APPLICATION DATE

July 2005

APPLICATION SITUATION

Damaged obsolete U.S. Royal 5.50-16 implement tread tire from J.I. Case 140w hay baler.

PROBLEM

Tire was damaged but cords still in good condition. No replacement available.

PRODUCTS

Belzona® 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Rubber

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona® Know-How System Leaflet MPT-10.

BELZONA FACTS

A wider tire would not fit the space between the baler and the tire. No manufacturer makes this size tire. A taller tire would cause an uneven hay pickup situation.

PICTURES

1. Damaged tire.
2. All loose rubber removed from tire.
3. Release agent was applied to a mold. Belzona® 2211 was applied to the tire and mold.
4. The tire repaired.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA®
Repair • Protect • Improve