

BELZONA AIR HANDLING FAN & SHROUD

CUSTOMER

Steel Company - Hamilton, Ontario - Canada

APPLICATION DATE

May 2003

APPLICATION SITUATION

Air Handling Fan

PROBLEM

Fan was constantly going out of balance due to particulate sticking to the blade.

PRODUCTS

Belzona® 1341 (Supermetalglide)

SUBSTRATE

Galvanized Steel

APPLICATION METHOD

The Application was carried out in accordance with Belzona Know-How System Leaflet FBC-2.

BELZONA FACTS

The fan was dynamically balanced before and after the application.

PICTURES

1. Fan blasted to 3-4 mil profile, white metal finish
2. Second coat of Belzona® 1341 completed on fan
3. Shroud coat completed



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

