

BELZONA EXCELS WHERE OTHERS FAIL!

CUSTOMER

Metal Forging Company - in the Northeast - U.S.A.

APPLICATION DATE

February 2003

APPLICATION SITUATION

Forging Machine Cam

PROBLEM

Forging machine cam failed, imitator product failed in one week.

PRODUCTS

Belzona® 1111 (Super Metal)

Belzona® 9111 (Cleaner/Degreaser)

SUBSTRATE

Steel

APPLICATION METHOD


The application was carried out in accordance with a modified version of Belzona Know-How Systems Leaflet MPT-12. Damaged areas were ground down. Following degreasing, Belzona® 1111 was applied, then ground/sanded back to profile.

BELZONA FACTS

Application saved tens of thousands of dollars in downtime, as disassembly of machine takes four days. Four months in service - PERFECT!

PICTURES

1. The Cam
2. Products being used
3. The completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

