

## NON-SLIP SAFETY SYSTEM IN HOSPITAL DISH WASHING ROOM

### CUSTOMER

Regional Hospital - British Columbia, Canada

### APPLICATION DATE

1999

### APPLICATION SITUATION

Hospital dish washing room floor

### PROBLEM

Inferior non-slip safety system

### PRODUCTS

Belzona® 1321 (Ceramic S-Metal)

Belzona® 9221 (Surefoot Aggregate)

### SUBSTRATE

Quarry tile

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

### BELZONA FACTS

Customer had contracted with another vendor to apply a non-slip safety system to the dish wash room floor. However, soon after completion of the application, it was found that the surface was extremely slippery. Belzona was approached to apply our standard system over this coating. Within a few months the inferior coating started to delaminate. We were contracted to remove all the red coating and apply a Belzona safety grip system directly to the original floor tiles. Photograph shows removal in progress.

### PICTURES

1. Previous failed system being stripped from the floor
2. View of application
3. View of another section of the application



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

