

LEAKY ROOF IS NO PROBLEM FOR BELZONA

CUSTOMER

Factory roof - Texas U.S.A.

APPLICATION DATE

2001 thru 2004

APPLICATION SITUATION

Sections of roof gutters

PROBLEM

Galvanized roof had numerous leaks around gutters. Previous attempts to stop leaks with conventional roofing materials failed.

PRODUCTS

Belzona® 3111 (Flexible Membrane)

Belzona® 3921 (GSC Surface Conditioner)

Belzona® 9311 (Reinforcing Membrane Sheets)

SUBSTRATE

Galvanized steel

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6.

BELZONA FACTS

Areas were cleaned, conditioned and two coats of Belzona® 3111 were brushed on. The total area protected with Belzona® 3111 was 8,000 sq. ft.

PICTURES

1. Conditioned and coated
2. Roof gutters
3. View of roof area
4. Another view of the gutters



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

