

QUARRY BELT REPAIR

CUSTOMER

Local Depot, Manchester UK

APPLICATION DATE

June 2000

APPLICATION SITUATION

Sand Belt

PROBLEM

600mm (23inch) tear in the belt

PRODUCTS

Belzona® 2311 (SR Elastomer)

SUBSTRATE

Rubber

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

BELZONA FACTS

The belt performed well until the plants closing in 2004.

PICTURES

1. Large Sand Belt
2. 600mm gash in the belt



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

