

BELZONA SEALS SF₆ LEAKS AT HYDROELECTRIC POWER STATION

CUSTOMER

Hydroelectric Power Plant, British Columbia, Canada

APPLICATION DATE

1993

APPLICATION SITUATION

SF₆ gas pipe

PROBLEM

SF₆ gas was leaking from the joints of the system requiring regular refilling.

PRODUCTS

Belzona® 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Steel

APPLICATION METHOD


Application carried out in accordance with Belzona Know-How System Leaflet GSS-4.

BELZONA FACTS

This application has been in service for many years with only minor repairs required. TOTAL TIME IN SERVICE - 13 YEARS.

PICTURES

1. Belzona® 2211 was injected into the gap between the 2 flanges.
2. Application shown in #1 completed.
3. Another flange sealed.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

